




Press the °C/°F button and Max Hold button together and hold them for about 5 seconds then release, the meter enters into password inputting mode.(The POWER button is to confirm the data you put in and to bring you to the next data setting. The °C/°F and Max Hold buttons are to adjust the value)



### **Calibration setting**

Press °C/°F and Max Hold to set the temperature error, press POWER to confirm and save the setting.




Temperature range( -50°C ~50°C)



### **Auto shut off setting**

Press °C/°F and Max Hold to input the auto shut off time, press Power to save the setting.



### **Password resetting**

Press °C/°F and Max Hold to input the new password, press Power to save the setting.

